

[Home](#) > List important physical characteristics of good bearing material.

List important physical characteristics of good bearing material.

Question:

List important physical characteristics of good bearing material.

Answer:

Physical characteristics of good bearing material- compressive strength, fatigue strength, embeddability, bondability, corrosion resistant, thermal conductivity, thermal expansion, conformability
